

MULE-HIDE REINFORCED EPDM MEMBRANE STRIPS ("RMS")

PRODUCT DESCRIPTION

Mule-Hide Reinforced EPDM Membrane Strips ("RMS") are 6" wide, 100' long strips of Mule-Hide reinforced EPDM membrane. The RMS is also available with a 3" butyl tape laminated to one side of the membrane strip eliminating the need for splice adhesives.

BASIC USES

Mule-Hide RMS strips are used in conjunction with Mule-Hide's 2" barbed seam plates and Mule-Hide HD fasteners as securement of the EPDM membranes at the base of parapet walls and curbs. The Mule-Hide RMS strips are installed beneath the EPDM field sheet and used as an alternate method to using the Mule-Hide All Purpose Bar. The RMS strip may be installed either horizontally or vertically. Mule-Hide's Tape Primer and either 3" wide In-Seam Tape or Butyl Splice Adhesive may be used to seam the EPDM field sheets to the RMS strips. An alternative is to use the 6" wide RMS w/Tape. When using the RMS w/Tape, Tape primer must be used to prime the EPDM membrane.

TYPICAL PROPERTIES AND CHARACTERISTICS

Sizes:	6" x 100' (150mm x 30.5m)
Packaging:	300 LF/Ctn. (150mm x 91.5m)
Thickness:	.045"-thick (1.14mm) Reinforced Membrane
Weight Per Carton:	40lbs. (18.1 Kg)

INSTALLATION INSTRUCTIONS

The RMS strips are loose laid along the base of the wall or curb and fastened to the deck utilizing the Mule-Hide 2" barbed seam plates and Mule-Hide HD fasteners. Maximum spacing of the fasteners shall not exceed 12" on center. Refer to Mule-Hide detail MHE-119 for proper placement of the plates and fasteners. When used for vertical attachment, the RMS strip must extend a minimum of 3" onto the horizontal surface. Refer to Mule-Hide Details MHE-124 & MHE-125.

The RMS strip and the field membrane are primed with Mule-Hide Tape Primer prior to the application of the Mule-Hide 3" In-Seam Tape or Butyl Splice Adhesive (Single Seal Adhesive is not approved for seaming the RMS to the field sheets). The RMS strips are spliced together following standard seaming procedures excluding the use of the Mule-Hide Lap Sealant.

When using the 6" RMS w/Tape, Tape Primer must be applied to only the field membrane. Refer to Details MHE-124A & MHE-125A.

TECHNICAL SERVICES

Contact Mule-Hide Products Co., Inc. at 608/365-3111 for additional information.

DISCLAIMER

The statements provided concerning the material shown are intended as a guide for material usage and are believed to be true and accurate. No statement made by anyone may supersede this information, except when done in writing by Mule-Hide Products Co., Inc. Since the manner of use is beyond our control, Mule-Hide does not make nor does it authorize anyone to make any warranty of merchantability or fitness for any particular purpose or any other warranty, guarantee or representation, expressed or implied, concerning this material except that it conforms to Mule-Hide's physical properties. Buyer and user accept the product under these conditions and assume the risk of any failure, any injury of person or property (including that of the user), loss or liability resulting from the handling, storage or use of the product whether or not it is handled, stored or used in accordance with the directions or specifications. Mule-Hide must be notified in writing of any claims and be given the opportunity to inspect the complaint or failure before repairs are made.

Form # PDS-E-5
Date 01/01/2007

MULE-HIDE PRODUCTS CO., INC.

P.O. Box 1057, Beloit, WI 53512-1057 • 608/365-3111 • Fax: 608/365-7852