

MULE-HIDE TPO WALKWAY ROLLS

PRODUCT DESCRIPTION

Mule-Hide TPO Walkway Rolls incorporate an aggressive, non-slip, diamond plate tread pattern of polyester reinforced TPO material that offers excellent tear and puncture resistance. Walkway Rolls are trimmed in safety yellow along the length of the sheet to better define the walkway area. The yellow edges are smooth without safety lugs to allow for easier welding.

BASIC USES

The Mule-Hide TPO Walkway Roll is designed to protect the TPO membrane in those areas exposed to repetitive foot traffic and other hazards. Mule-Hide specifications require the use of such a product in walkway concentration points (i.e., roof hatches, access doors, rooftop ladders, etc.) regardless of traffic frequency. Walkways must also be installed if regular maintenance (once a month or more) is necessary to service rooftop equipment.

SPECIFICATIONS

Color:	White, Gray, Tan
Surface Texture:	Diamond Plate traction surface
Material:	Polyester reinforced TPO material
Sizes:	34" x 50' (76cm X 15.2m)
Weight:	88 lbs per roll
Thickness:	180-mil overall (4.06 mm)
Tensile Strength:	600 psi as per ASTM D638
Tear Strength:	100 lbf/in as per ASTM D624

PACKAGING AND STORAGE

Each roll is individually bagged. Nine rolls per skid. Store rolls in a clean, cool, dry location.

INSTALLATION INSTRUCTIONS

If membrane or walkway roll has been exposed for over 7 days, use Weathered Membrane Cleaner and a Scotch-Brite Pad to prepare the area to be welded to the walkway material. Once the cleaner has dried completely, position the walkway material. Cut the Walkway Rolls into maximum 10-foot lengths and position with a minimum 1-inch gap between adjacent pieces to allow for water drainage. Cut the Walkway Roll so a 4-inch minimum gap is created over any field splices. (Since the attachment of the Walkway Roll to the membrane is permanent, this will allow access to the field seams) Using an automated welder, weld all four sides of the walkway material to the membrane. (Typically the same speed and temperature settings will be used for this procedure as for welding membrane to membrane. A test weld is always recommended prior to performing welds to the installed membrane). A hand held welder may be utilized, however, productivity will be decreased.

PRECAUTIONS

TPO Walkway Rolls must be installed textured side up. Do not install Walkway over field seams or flashing seams.

TECHNICAL SERVICES

Contact Mule-Hide Products Co., Inc. at 608/365-3111 for technical service information.

DISCLAIMER

The statements provided concerning the material shown are intended as a guide for material usage and are believed to be true and accurate. No statement made by anyone may supersede this information, except when done in writing by Mule-Hide Products Co., Inc. Since the manner of use is beyond our control, Mule-Hide does not make nor does it authorize anyone to make any warranty of merchantability or fitness for any particular purpose or any other warranty, guarantee or representation, expressed or implied, concerning this material except that it conforms to Mule-Hide's physical properties. Buyer and user accept the product under these conditions and assume the risk of any failure, any injury of person or property (including that of the user), loss or liability resulting from the handling, storage or use of the product whether or not it is handled, stored or used in accordance with the directions or specifications. Mule-Hide must be notified in writing of any claims and be given the opportunity to inspect the complaint or failure before repairs are made.

MULE-HIDE PRODUCTS CO., INC.